

# ***Airport Operations Report: June 2018***

- 1) All runway lights, PAPI, and beacon tower are now operational.

Van Ert was called on 6/8 to check on the status of the runway lights, and PAPI system.

They had no idea that the PAPI system was inoperable, and were aware of runway light issues. Set up an appointment for 6/13 for a site visit.

After calling Van Ert, I investigated further into the PAPI-32 problem of tripping the circuit breaker during operation. I found loose wires on the PAPI-32 contactor in the terminal. Tightened wire connections. Tightened connections on contactor in electrical panel out on runway. On 6/11, notified Van Ert that PAPI-32 had been working for 3 days and may not need servicing on 6/13 visit.

On 6/13 Jim from Van Ert and myself replaced the circuit boards in 6 runway lights with circuit boards out of new spare lights.

One runway light was left in place which was originally tagged as damaged. It was operational, but it was much brighter than the other lights. On 6/21, I replaced that pc board.

I fixed 2 broken runway lights damaged during winter snow removal.

Beacon light is working after I replaced lamps with 2 used and cleaned lamps. No new spares in garage. New lamps on order. Closed NOTAM 06/214.

- 2) Replaced both stop signs by electronic gate entry. Old signs were badly cracked, and faded. Town crew provided signs.
- 3) Ongoing weekly mowing operations.
- 4) Owner of Hangar #15 announced he wanted to rent his hangar. Kept contact information. Passed onward to several pilots.
- 5) Red truck heater/ defroster blower problems. Replaced heater blower resistor. Blew sand, dust and leaves out of ducts and fan.

Reattached front valance back to bumper. Had been taped together.

New emergency light is on order. Current light is very noisy while in operation.

Speedometer is still inoperative. Have not investigated.

## ***Airport Operations Report: June Page 2***

- 6) No change in GCO status.
- 7) Asphalt repair?
- 8) AWOS System: Installed new cellular radio modem received on 6/20. New modem is 4G. Old 3G.
- 9) Fire Inspection: All hangars, terminal, and garages were inspected. No major discrepancies. Notified owners of minor infractions.

***Airport Operations Report: June Page 3***

Airport credit card purchases: \$0 YTD: \$0

Current 100LL fuel price at D25 is **\$4.59/ gal.**

100LL Fuel Purchase: **8400 gal @ \$3.8541 = \$32,374.8**

100LL Fuel sales: **856.908 gal for \$3901.7** YTD: **1827.23 gal. = \$8097.2**

YTD 2018 diesel fuel used: 380.21 gal.

Approximately 10764 gallons of 100LL on hand.

\$117.00 received in Courtesy Car Rental / Tie Downs

Staff hours worked: 208.75 hrs.

Manager hours worked: 65.5 hrs.

Total hours: 274.25