

Airport Operations Report: Sept. 2019

- 1) Mowing operations in effect about once every 3 weeks. Weekly around terminal. One more mowing should be all that is needed before winter.
- 2) Crack sealing was completed on runway 14/32, approach, apron, hangar areas, and Airport Road to front of terminal. Work was completed in a week. Quality of work done with the sealing was good. Asphalt crumbles left everywhere after completion was not appreciated.
- 3) Sprinkler system around terminal, and community garden has been drained, and blown out. Ready for winter. The community garden uses the airport garage well pump.
- 4) The Fire Extinguisher Inspection has finally been completed. Many extinguishers needed to be replaced for being too old and not certifiable. Airport manager will send out detailed billing to Hangar Presidents. Town was billed for all inspections.
- 5) Contacted BJ Bauers again to possibly determine AWOS weather station power problem. Tower lights, and weather system lose power only during sub-zero temps.
- 6) Electronic gate card validation. There are 83 gate cards that remain outstanding/ unverified.
- 7) 100 LL levels are getting low. (Approx. 1850 on hand 10/1.)
Current fuel prices as of 10/6 for 8200 gal. load are \$4.1045/gal.
Current fuel prices as of 10/6 for 4000 gal. load are \$4.2352/gal.

